



REPORT OF TRAFFIC ACCIDENT INVOLVING AN AUTONOMOUS VEHICLE

DMV USE ONLY
AVT NUMBER
NAME

Instructions: Please print within the spaces and boxes on this form. If you need to provide additional information on a separate piece of paper(s) or you include a copy of any law enforcement agency report, please check the box to indicate "Additional Information Attached."

- Write **unk (for unknown)** or **none** in any space or box when you do not have the information on the other party involved.
- Give insurance information that is complete and which correctly and *fully* identifies the **company** that issued the insurance policy or surety bond, or whether there is a certificate of self-insurance.
- Place the National Association of Insurance Commissioners (NAIC) number for your Insurance or Surety Company in the boxes provided. The NAIC number should be located on the proof of insurance provided by you company or you can contact your insurer for that information.
- Identify any person involved in the accident (driver, passenger, bicyclist, pedestrian, etc) that you saw was injured or complained of bodily injury or know to be deceased.
- Record in the PROPERTY DAMAGE line any damage to telephone poles, fences, street signs, guard post, trees, livestock, dogs, buildings, parked vehicles, etc., including a description of the damage.
- Once you have completed this report, please mail to: Department of Motor Vehicles, Occupational Licensing Branch, P.O. Box 932342, MS: L224, Sacramento, CA 94232-3420

SECTION 1 — MANUFACTURER'S INFORMATION

MANUFACTURER'S NAME Google Auto LLC		AVT NUMBER
BUSINESS NAME Google		TELEPHONE NUMBER
STREET ADDRESS	CITY	STATE ZIP CODE

SECTION 2 — ACCIDENT INFORMATION

DATE OF ACCIDENT 09/07/2016	TIME OF ACCIDENT 6:47 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM	VEHICLE YEAR 2015	MAKE GOOGLE	MODEL SELF DRIVING CAR
LICENSE PLATE NUMBER	VEHICLE IDENTIFICATION NUMBER		STATE VEHICLE IS REGISTERED IN	
ADDRESS/LOCATION OF ACCIDENT Nita Ave. and San Antonio Rd.		CITY Palo Alto	COUNTY Santa Clara	STATE ZIP CODE CA 94306
Vehicle was: <input checked="" type="checkbox"/> Moving <input type="checkbox"/> Stopped in Traffic		Involved in the Accident: <input type="checkbox"/> Pedestrian <input type="checkbox"/> Bicyclist <input type="checkbox"/> Other _____		NUMBER OF VEHICLES INVOLVED 2
DRIVER'S FULL NAME (FIRST, MIDDLE, LAST)		DRIVER LICENSE NUMBER		STATE DATE OF BIRTH
INSURANCE COMPANY NAME OR SURETY COMPANY AT TIME OF ACCIDENT		POLICY NUMBER		
COMPANY NAIC NUMBER		POLICY PERIOD FROM _____ TO _____		

SECTION 3 — OTHER PARTY'S INFORMATION

VEHICLE YEAR 2014	MODEL Mercedes Sprinter			
LICENSE PLATE NUMBER	VEHICLE IDENTIFICATION NUMBER	STATE VEHICLE IS REGISTERED IN		
Vehicle was: <input checked="" type="checkbox"/> Moving <input type="checkbox"/> Stopped in Traffic		Involved in the Accident: <input type="checkbox"/> Pedestrian <input type="checkbox"/> Bicyclist <input type="checkbox"/> Other _____		NUMBER OF VEHICLES INVOLVED 2
DRIVER'S FULL NAME (FIRST, MIDDLE, LAST)		DRIVER LICENSE NUMBER		STATE DATE OF BIRTH
INSURANCE COMPANY NAME OR SURETY COMPANY AT TIME OF ACCIDENT		POLICY NUMBER		
COMPANY NAIC NUMBER		POLICY PERIOD FROM _____ TO _____		

Additional information attached.



SECTION 4 — INJURY/DEATH, PROPERTY DAMAGE

NAME (FIRST, MIDDLE, LAST)

ADDRESS CITY STATE ZIP CODE

CHECK ALL THAT APPLY Injured Deceased Driver Passenger Bicyclist Property

NAME (FIRST, MIDDLE, LAST)

ADDRESS CITY STATE ZIP CODE

CHECK ALL THAT APPLY Injured Deceased Driver Passenger Bicyclist Property

PROPERTY DAMAGE

PROPERTY OWNER'S NAME

TELEPHONE NUMBER

()

STREET ADDRESS

CITY

STATE ZIP CODE

WITNESS NAME

TELEPHONE NUMBER

()

STREET ADDRESS

CITY

STATE ZIP CODE

WITNESS NAME

TELEPHONE NUMBER

()

STREET ADDRESS

CITY

STATE ZIP CODE

Additional information attached.

SECTION 5 — ACCIDENT DETAILS - DESCRIPTION

Autonomous Mode Conventional Mode

A Google prototype autonomous vehicle ("Google AV") proceeding westbound in autonomous mode on Nita Avenue in Palo Alto was involved in an accident. The Google AV came to a stop at the intersection of San Antonio Road, then, in preparation for making a right turn on San Antonio Road, began to gradually advance forward in order to gain a better view of cross-traffic. A 12-passenger shuttle van waiting immediately behind the Google AV then advanced forward at approximately 7 mph and collided with the rear bumper of the Google AV. The Google AV was travelling at approximately 3 mph at the time of the collision. The Google AV experienced minor damage to its rear bumper and hatch. The other vehicle experienced minor damage to its front bumper and right headlight. There were no injuries reported at the scene by either party.

Additional information attached.

SECTION 6 — CERTIFICATION

I certify (or declare) under penalty of perjury under the laws of the State of California that the foregoing is true and correct.

I further certify that I am the authorized Administrator of the program for the above named employer.

PROGRAM DIRECTOR/AUTHORIZED REPRESENTATIVE PRINTED NAME AND TITLE

TELEPHONE NUMBER

MANAGER

SIGNATURE

DATE SIGNED

X

